

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

| | | | |
|--|---|--|-----------------------------------|
| 1. TITLE END OF LIFE ANNOUNCEMENT FOR SMD# 5962-94754, UT22VP10 UNIVERSAL RADPAL™ | | 2. DOCUMENT NUMBER SPO-2020-D-0007 | |
| | | 3. DATE (Year, Month, Date) 2020 JUNE 02 | |
| 4. MANUFACTURER NAME AND ADDRESS CAES 4350 CENTENNIAL BOULEVARD COLORADO SPRINGS, COLORADO 80907-3486 | | 5. MANUFACTURER POINT OF CONTACT (NAME) Bruce Massey | |
| | | 6. MANUFACTURER POINT OF CONTACT TELEPHONE 719-594-8466 | |
| | | 7. MANUFACTURER POINT OF CONTACT EMAIL bruce.massey@cobhamaes.com | |
| 8. CAGE CODE 65342 | 9. MANUFACTURER FINAL ORDER DATE December 31, 2021 | 10. PRODUCT IDENTIFICATION CODE RC01, RC02, RC03 | 11. BASE PART UT22VP10 |
| 12. BLANK | | 13. SMD NUMBER 5962-94754 | 14. DEVICE TYPE DESIGNATOR All |
| | | 15. RHA LEVELS All | 16. QML LEVEL Q, V |
| | | 17. NON QML LEVEL Prototype | 18. GIDEP NUMBER GB4-D-20-0007 |

19. COMMENTS

CAES IS ISSUING THIS DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES (DMSMS) NOTICE TO ANNOUNCE THE UT22VP10 UNIVERSAL RADPAL™ (SMD#5962-94754) HAS REACHED END OF LIFE (EOL). CAES EXPECTS TO DEplete ALL INVENTORY BY DEC 2021. CAES WILL ACCEPT ORDERS ON A FIRST-COME, FIRST-SERVED BASIS THROUGH DECEMBER 2021 OR WHILE SUPPLIES LAST.

CAES IS NOT PLANNING TO MIGRATE THE PRODUCT TO MAINTAIN PRODUCTION. CAES DOES NOT HAVE A DIRECT REPLACEMENT TO 5962-94754. IF CUSTOMERS SEEK A FORM-FIT-FUNCTIONAL REPLACEMENT, CAES WILL DISCUSS POSSIBLE ASIC CONVERSION OF THE CURRENT UT22VP10. IF AN ASIC CONVERSION IS DESIRED, PLEASE CONTACT YOUR LOCAL CAES SALES REPRESENTATIVE.

APPLICABLE PART NUMBERS ARE LISTED IN TABLE 1, SHEET 2, 3, BELOW

TABLE I

| MANUFACTURER PART NUMBER | GOVERNMENT PART NUMBER |
|--------------------------|------------------------|
| UT22VP10C-25UCA | 5962H9475401QXA |
| UT22VP10C-25UCC | 5962H9475401QXC |
| UT22VP10C-25UCA | 5962H9475401VXA |
| UT22VP10C-25UCC | 5962H9475401VXC |
| UT22VP10C-25PCA | 5962H9475401QLA |
| UT22VP10C-25PCC | 5962H9475401QLC |
| UT22VP10C-25PCA | 5962H9475401VLA |
| UT22VP10C-25PCC | 5962H9475401VLC |
| UT22VP10C-25WCA | 5962H9475401QYA |
| UT22VP10C-25WCC | 5962H9475401QYC |
| UT22VP10C-25WCA | 5962H9475401VYA |
| UT22VP10C-25WCC | 5962H9475401VYC |
| | |
| UT22VP10T-25UCA | 5962H9475402QXA |
| UT22VP10T-25UCC | 5962H9475402QXC |
| UT22VP10T-25UCA | 5962H9475402VXA |
| UT22VP10T-25UCC | 5962H9475402VXC |
| UT22VP10T-25PCA | 5962H9475402QLA |
| UT22VP10T-25PCC | 5962H9475402QLC |
| UT22VP10T-25PCA | 5962H9475402VLA |
| UT22VP10T-25PCC | 5962H9475402VLC |
| UT22VP10T-25WCA | 5962H9475402QYA |
| UT22VP10T-25WCC | 5962H9475402QYC |
| UT22VP10T-25WCA | 5962H9475402VYA |
| UT22VP10T-25WCC | 5962H9475402VYC |
| | |
| UT22VP10C-20UCA | 5962H9475403QXA |
| UT22VP10C-20UCC | 5962H9475403QXC |
| UT22VP10C-20UCA | 5962H9475403VXA |
| UT22VP10C-20UCC | 5962H9475403VXC |
| UT22VP10C-20PCA | 5962H9475403QLA |
| UT22VP10C-20PCC | 5962H9475403QLC |
| UT22VP10C-20PCA | 5962H9475403VLA |
| UT22VP10C-20PCC | 5962H9475403VLC |
| UT22VP10C-20WCA | 5962H9475403QYA |
| UT22VP10C-20WCC | 5962H9475403QYC |
| UT22VP10C-20WCA | 5962H9475403VYA |
| UT22VP10C-20WCC | 5962H9475403VYC |
| | |
| UT22VP10T-20UCA | 5962H9475404QXA |
| UT22VP10T-20UCC | 5962H9475404QXC |
| UT22VP10T-20UCA | 5962H9475404VXA |
| UT22VP10T-20UCC | 5962H9475404VXC |
| UT22VP10T-20PCA | 5962H9475404QLA |
| UT22VP10T-20PCC | 5962H9475404QLC |
| UT22VP10T-20PCA | 5962H9475404VLA |
| UT22VP10T-20PCC | 5962H9475404VLC |
| UT22VP10T-20WCA | 5962H9475404QYA |
| UT22VP10T-20WCC | 5962H9475404QYC |
| UT22VP10T-20WCA | 5962H9475404VYA |
| UT22VP10T-20WCC | 5962H9475404VYC |
| | |
| UT22VP10E-25UCA | 5962H9475405QXA |
| UT22VP10E-25UCC | 5962H9475405QXC |
| UT22VP10E-25UCA | 5962H9475405VXA |
| UT22VP10E-25UCC | 5962H9475405VXC |
| UT22VP10E-25PCA | 5962H9475405QLA |
| UT22VP10E-25PCC | 5962H9475405QLC |
| UT22VP10E-25PCA | 5962H9475405VLA |
| UT22VP10E-25PCC | 5962H9475405VLC |
| UT22VP10E-25WCA | 5962H9475405QYA |
| UT22VP10E-25WCC | 5962H9475405QYC |
| UT22VP10E-25WCA | 5962H9475405VYA |
| UT22VP10E-25WCC | 5962H9475405VYC |

| | |
|-----------------|-----------------|
| UT22VP10E-20UCA | 5962H9475406QXA |
| UT22VP10E-20UCC | 5962H9475406QXC |
| UT22VP10E-20UCA | 5962H9475406VXA |
| UT22VP10E-20UCC | 5962H9475406VXC |
| UT22VP10E-20PCA | 5962H9475406QLA |
| UT22VP10E-20PCC | 5962H9475406QLC |
| UT22VP10E-20PCA | 5962H9475406VLA |
| UT22VP10E-20PCC | 5962H9475406VLC |
| UT22VP10E-20WCA | 5962H9475406QYA |
| UT22VP10E-20WCC | 5962H9475406QYC |
| UT22VP10E-20WCA | 5962H9475406VYA |
| UT22VP10E-20WCC | 5962H9475406VYC |
| | |
| UT22VP10E-15UCA | 5962H9475407QXA |
| UT22VP10E-15UCC | 5962H9475407QXC |
| UT22VP10E-15UCA | 5962H9475407VXA |
| UT22VP10E-15UCC | 5962H9475407VXC |
| UT22VP10E-15PCA | 5962H9475407QLA |
| UT22VP10E-15PCC | 5962H9475407QLC |
| UT22VP10E-15PCA | 5962H9475407VLA |
| UT22VP10E-15PCC | 5962H9475407VLC |
| UT22VP10E-15WCA | 5962H9475407QYA |
| UT22VP10E-15WCC | 5962H9475407QYC |
| UT22VP10E-15WCA | 5962H9475407VYA |
| UT22VP10E-15WCC | 5962H9475407VYC |
| | |
| UT22VP10T-15UCA | 5962H9475408QXA |
| UT22VP10T-15UCC | 5962H9475408QXC |
| UT22VP10T-15UCA | 5962H9475408VXA |
| UT22VP10T-15UCC | 5962H9475408VXC |
| UT22VP10T-15PCA | 5962H9475408QLA |
| UT22VP10T-15PCC | 5962H9475408QLC |
| UT22VP10T-15PCA | 5962H9475408VLA |
| UT22VP10T-15PCC | 5962H9475408VLC |
| UT22VP10T-15WCA | 5962H9475408QYA |
| UT22VP10T-15WCC | 5962H9475408QYC |
| UT22VP10T-15WCA | 5962H9475408VYA |
| UT22VP10T-15WCC | 5962H9475408VYC |